

TO BE FILLED BY THE INSPECTING OFFICER

- 1 Name of Officer : SHINE.P.R
2 Name Of School : Villa Nazareth English Mediam School ,Palaikonam.
3 Location with Edn. Dist/Sub.Dist : Palaikonam, Attingal/ Nedumangadu
4 Classification of Building and size (basis for :
i. Permanent (Single or multi storied) : 1) 53.50 X 10.05 X 7.20 M + 2.00 X 36.10X6.65X7.20
+ 37.05X6.45X7.20M+2.85MM wide Verandah
(Double Storied R.C.C Roof Building)
ii. Semi permanent :
iii. Temporary :
5 Period for which the certificate issued : 2025- 2026
6 Nature of defect, if any :
a. Foundation and basement :
b. Superstructure :
c. Doors and Windows :
d. Wood work wrought and put up : Nil
e. Roof :
f. Flooring :
g. Misc. (Cracks etc) :
7 Any major defects noticed which will render the : No
8 Whether maintenance work have been : Yes
9 Whether structure is sound or not for : *Structure is sound to conduct classes under normal*

Note

- 1 The stability of structure should be examined also with reference to location, altitude, intensity of wind exposure to flood etc.
- 2 Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.
- 3 All directions given as per Circular No W(1)39792/2017/DGE dtd 05.10.2021 should be compiled before opening of the classes

Certified that the school was inspected by me on 26.05.2025 and found fit to conduct classes or the academic year 2025 - 2026 for the reason stated above.

Place: Aryanadu
Date: 27.05.2025

Signature
Designation

Assistant ENGINEER
LID & EW SECTION
ARYANAD GRAMA PANCHAYAT

